

## Inspection Summary

Permit #: PRCOM20161058, Building Permit - Commercial  
Address: 1200 SE HAMBLEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Gas Piping Inspection - Commercial</b>	Mike Copeland	Passed	Wednesday, August 23, 2017
<b>Gas Service Inspection - Commercial</b>	Mike Copeland	Passed	Wednesday, August 23, 2017

**Comments:**