LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20170794, Public Works Infrastructure Permit - Residential Eagle Creek 15th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Storm - Pipe	Tom Chandler	Partial	Thursday, August 24, 2017
Informational			
-	2017 2:47 PM Grout and wr veen top section and bottom		sewer
DEI-Grading/Excavation/Fill Inspection	Tom Chandler	Partial	Thursday, August 24, 2017
Informational			
-	2017 2:44 PM Fill being places well. Testing for lift being p	•	
DEI-Grading/Excavation/Fill Inspection	Tom Chandler	Partial	Thursday, August 24, 2017
Informational			
-	2017 10:07 AM Fill being plates of the second se Isson on-site for testing. (2) I		
DEI-Grading/Excavation/Fill Inspection	Tom Chandler	Partial	Thursday, August 24,

Informational

1 Tom Chandler 08/24/2017 11:48 AM Finished another lift between station 86 and station 88. Olsson on site for testing. Will continue to fill between station 87 and station 89 this afternoon.

Comments:

220 SE Green Street | Lee's Summit, MO 64063 | 816.969.1800 | 816.969.1810 Fax | cityofLS.net/Development