Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20170810, Building Permit - Residential Address: 1832 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Dale Carter Failed Monday, September 11, 2017

Residential

Corrective Action Required

. Misc 1. BSMT & 2nd FLR: Elec nail guards where marked with red 'X'.

2. BSMT: Firestop along tops of walls and at end of ceiling

furr-out.

3. BSMT: Anchor columns.

4. 1st FLR: Firestop tops of DWV chases at rear of Living Room &

Garage.

5. 1st FLR: Notched floor joist over rear of Living Room.

6. 1st FLR: Nail stud shoes at kitchen.

7. 2nd FLR: More than 2 consecutive studs bored at master bath.

Comments: