Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20160939, Building Permit - Commercial Address: 3320 NE WILSHIRE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Above Ceiling Inspection	Khanh Nguyen	Partial	Wednesday, September 13, 2017	
Corrective Action Require 1 Misc	CEILIN	EILING SPACE BELOW RATED CEILING: ONE A&C CORRIDOR-OK		
	-ZONE	AQC CORRIDOR-OR		
	-COMF	*ZONE B NORTH SIDE OF COMMON HEARTH AREA : -COMPLETE MECHANICAL DUCTING TO CEILING REGISTERS -INSIDE WOMEN RESTROOM, COVER EXPOSED WOOD WITH ROCK		
	*SOUT	*SOUTH SIDE NOT READY		

Comments: