Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161178, Building Permit - Commercial Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	John Borns	Partial	Thursday, September 14, 2017
Partial Correction1MiscPartial Correction2Misc		~110' NW FOR BL; ONE 1" FROM	PLAN IN PERMIT PRINT SET: #1 22; [23; 24; 25; 26; 27; NCHED PVC CONDUIT: FROM E 3/4" TO 28' WEST CONN TO 5' NE FOR BL; ONE 1" ~80' M BL TO BL; ONE 3/4" FROM LP#7 PL#7 NORTH 20' TO Q-BOX CLOCATION NW TO BL LOCATION ROUND ROD FOR LP#7 LAID IN
		#11 TO #12; #13 TO #9 TO #10; F #6 TO 15' WEST	ROM #12 TO #14 TO #15; FROM
Above Ceiling Inspection	John Borns	Partial	Thursday, September 14, 2017
Partial Correction 1 Misc		OK TO COVER WHEN READY GW ABOVE-CEILING SYSTEMS @ FOL 107; C104 - C108; 111; 112; C115 123; C131 - C134; C137 - C138; C C154 - C159; FOUR CLOUD CEILII SOFFITS AT 113 INCLUDING EAST RATED WALL AT SOUTH YET TO E	LOWING SPACES: C102; 104; 106; 5; 116; C118; C119; C121 - C129; 140; C142 - C144; C146 - C149; NGS AT AEROBICS 157; C163; F 12' (RD PENETRATION OF

		SOFFITS AT 126 EXCEPT S 10'; CEILING @ 129; 141; 147; 148;
		CORR 108; 109; REVISIONS @ 124; CORR 144; AV 110; WOMEN'S
		143; CORR 116; MEN'S LOCKER 145 INCLUDING SOUTH SHOWER
		UNIT; PORTE COCHERE; 101 CEILING ONLY; SOFFITS AT N & S
		ENDS OF 102;
Partial C	orrection	
2	Misc	OK TO COVER WHEN READY ACT CEILING FRAMING +
		ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: 118; 119; 121;
		122; 163; [104; 105; 148;

Comments: