

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161178, Building Permit - Commercial

Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Gas Piping Inspection - Commercial	John Borns	Partial	Friday, September 15, 2017

Partial Correction

1 Misc

GAS FEEDER PIPE FROM DISTRIBUTION LINE AT OBRIEN RD TO S WALL OF BLDG HELD STEADY AT 95 PSI FOR >20 MINUTES. PIPE DEPTH IN TRENCH OK TO COVER WHEN READY.

Partial Correction

2 Misc

PRESSURE TEST ON INTERIOR & ROOFTOP GAS PIPING HELD STEADY AT 30 PSI FOR >30 MINUTES. OK FOR USE CONTINENT ON INSPECTION/APPROVAL OF ROOFTOP PIPING.

Above Ceiling Inspection

John Borns

Partial

Friday, September 15, 2017

Partial Correction

1 Misc

OK TO COVER WHEN READY GWB CEILING / SOFFIT FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: C102; 104; 106; 107; C104 - C108; 111; 112; C115; 116; C118; C119; C121 - C129; 123; C131 - C134; C137 - C138; C140; C142 - C144; C146 - C149; C154 - C159; FOUR CLOUD CEILINGS AT AEROBICS 157; C163; SOFFITS AT 113 INCLUDING EAST 12' (RD PENETRATION OF RATED WALL AT SOUTH YET TO BE RESOLVED); SOFFITS AT 118; SOFFITS AT 126 EXCEPT S 10'; CEILING @ 129; 141; 147; 148; CORR 108; 109; REVISIONS @ 124; CORR 144; AV 110; WOMEN'S 143; CORR 116; MEN'S LOCKER 145 INCLUDING SOUTH SHOWER UNIT; PORTE COCHERE; 101 CEILING ONLY; SOFFITS AT N & S ENDS OF 102;

Partial Correction

2 Misc

OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: 118; 119; 121;

122; 163; [147; 158;

Comments: