## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRRES20170715, Building Permit - Residential Address: 3352 SW JESSIE LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Gas Service Inspection - Dale Carter Not Ready Wednesday, September 27,

Residential 2017

**Corrective Action Required** 

1 Misc No pressure

All Rough Inspection - Dale Carter Not Ready Wednesday, September 27,

Residential 2017

Corrective Action Required

1 Misc -PLEASE HAVE APPROVED PLANS ON SITE FOR INSPECTION

-GAS: NO PRESSURE

-ELECTRIC: SERVICE CONDUCTORS NOT CONNECTED

REPAIR EROSION CONTROL BEFORE FURTHER INSPECTION

**Electrical Service** Dale Carter Not Ready Wednesday, September 27,

Inspection - Residential 2017

**Corrective Action Required** 

1 Misc Service conductors not connected in main panel.

**Erosion Control** Dale Carter Failed Wednesday, September 27,

2017

Corrective Action Required

1 Misc Repair erosion control before further inspection.

## **Comments:**