

# Certificate of Occupancy

---

**Permit #:** PRRES20162317  
**Address:** 1317 NE BRANDYWINE RD, LEES SUMMIT, MO 64064  
**Inspected On:** Thursday, September 28, 2017  
**Inspected By:** Khanh Nguyen

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

| Inspection:                                                            | Inspector:  | Outcome: | Date:                           |
|------------------------------------------------------------------------|-------------|----------|---------------------------------|
| <b>Occupancy Inspection -</b> Khanh Nguyen<br><b>Codes Residential</b> | Full C of O |          | Thursday,<br>September 28, 2017 |

**Comments:**