Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171896, Building Permit - Residential Address: 1820 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Dale Carter Failed Tuesday, October 10, 2017

Residential

Corrective Action Required

Misc
BSMT: Support DWV over entry door to unfinished area.

5. BSMT: Firestop change in ceiling height at entry door to unfinished area. *Either solid block, or insulation should extend

16" below level where solid blocking would go.

6. BSMT: Firestop over deadspace behind shower. *solid

blocking

14. 2nd FLR: Nail siding. *east and west walls

17. 2nd FLR: Fully install/nail snow blocking. *master closet

Comments: