

# Certificate of Occupancy

---

**Permit #:** PRCOM20171833  
**Address:** 622 SW 3RD ST, Unit:M, LEES SUMMIT, MO 64063  
**Inspected On:** Wednesday, October 11, 2017  
**Inspected By:** John Borns

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Wednesday, October 11, 2017

**Comments: RESTROOM IN EXPANSION AREA IS EXISTING AND IS NOT COMPLIANT WITH ACCESSIBILITY STANDARDS.**