

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171501, Building Permit - Residential
Address: 1804 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Friday, October 13, 2017

Corrective Action Required

1	Misc	<ol style="list-style-type: none">1. Firestopping has not been completed.2. BSMT: Install window.3. BSMT: Anchor column.4. 1st FLR: Sill-plate anchor in garage.5. 2nd FLR: Add purlin leg over bathroom bearing on quadruple-2x12.6. Nail siding at snow-blocked locations.
---	------	---

Electrical Service Inspection - Residential	Dale Carter	Passed	Friday, October 13, 2017
--	-------------	--------	--------------------------

Gas Piping Inspection - Residential	Dale Carter	Passed	Friday, October 13, 2017
--	-------------	--------	--------------------------

Gas Service Inspection - Residential	Dale Carter	Passed	Friday, October 13, 2017
---	-------------	--------	--------------------------

Comments: