

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20171689, Building Permit - Commercial

Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
In-wall Inspection	John Borns	Partial	Wednesday, October 18, 2017

Partial Correction

1	Misc	OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING + IN-WALL SYSTEMS AT FOLLOWING SPACES/LOCATIONS: ROWS F THROUGH J, AND 17.3 THROUGH 16; STORAGE RM 1A226; RESTROOM 1A232; STORAGE RM 1A250; RESTROOM 1A217; CLEAN RM 1A218; EXTERIOR WALL AT 1A263 & 1A268; [261; 262.1; 262.2; 267; [218 COMPLETE; 263 COMPLETE; 210 COMPLETE; 258; 260;
---	------	--

Rated Assembly Inspection	John Borns	Partial	Wednesday, October 18, 2017
----------------------------------	------------	---------	-----------------------------

Partial Correction

1	Misc	OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT: FIRE-RATED WALLS AT: OUTSIDE 1A250 AND 1A226 FROM CORNER TO DOOR TOP-OUT ONLY AT: 1A212 W WALL AT DOOR #212.3; 218 N, W, S WALLS: 258 W WALL; 260 W WALL; 261 W WALL; 262.1 N, W WALLS; 262.2 W WALL; 1A232 S&E TO 10' AFF; 1A250 S/E/N TO 10' AFF; 226 COMPLETE; ON F' FROM (15.6) TO (16.4) CORRIDOR FACE ONLY; [TOP-OUT COMPLETE @ 250; 255 N AT BACKSIDE OF 262.1; 257; 261; 262.1; 263;
---	------	--

Comments: