## **Development Services Department**

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Inspection Summary**

Permit #:PRCOM20161180, Building Permit - Commercial

Address: 501 NW SHAMROCK AVE, LEES SUMMIT, MO 64081521 NW SHAMROCK AVE, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Rated Assembly Inspection	John Borns	Partial	Monday, October 23, 2017	
Partial Correction 1 Misc		OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT CEILING AND WALLS AT:		
Partial Correction		LINK CORRIDOR A111 SOUTH 36' + "B"-TO-COMMONS LINK; CORR 205 WALLS + LID; CORR A-305 LID & WALLS; CORR 405; CORR 219; CORR 207; LOBBY 205; CORR 219; LOBBY 224;		
		UNITS/ROOMS: 201; 203; 204; 209; 210; 212; 217; 218; 221; 222; 225; 226; 227; 228; 229; 231; 232; 233; 234;		
		UNITS/ROOMS: 303; 304; 332; 333; <b>[301; 334;</b> UNITS/ROOMS: 403; 404; 432; 433; UNITS/ROOMS:		
	ABOVE CEILING AT BACKSIDE OF STAIRWELL WALL AT: 201; 222; 301; 322; 206;			
2 Misc		AT:	IRE-STOP PRE-ROCK AT SHOWERS/TUBS	
		201; 203; 204; 206; 217; 2 233; 234;	18; 221; 222; 225; 226; 227; 228; 232;	
		301; 303; 304; 306; 308; 3 333; 334;	18; 321; 322; 325; 326; 327; 328; 332;	
	401; 403; 404; 406; 408; 418; 421; 422; 425; 426; 427; 428; 432;		18; 421; 422; 425; 426; 427; 428; 432;	

433; 434;

## [506; 508; 517/518; 520; 521; 522; 525; 526; 527;

**Above Ceiling** John Borns Partial Monday, October 23, 2017 **Inspection** 

**Partial Correction** 

3 Misc OK TO COVER WHEN READY ACT CEILING FRAMING +

ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES: [LINK

**CORRIDOR A111 EXCEPT N 4';** 

**All Rough Inspection -** John Borns Partial Monday, October 23, 2017

Commercial

**Partial Correction** 

L Misc OK TO COVER CORRIDOR/LOBBY WALLS AND CEILINGS AT: LINK

CORRIDOR A111; NW CORRIDOR; CORR 305; CORR LVL 4; CORR

219; CORR 307/319; [LOBBY 409;

**Partial Correction** 

2 Misc OK TO COVER WHEN READY WALL AND CEILING FRAMING +

SYSTEMS TO BE ENCLOSED AT:

1ST FLOOR SPACES: 108; 109;

2ND FLOOR UNITS/SPACES: 201; 203; 204; 206; 207; 208; 209; 212; 213; 214; 216; 217\*; 218\*; 219; 232; 233; ABOVE CEILING AT

STAIRWELL COMMON WALL AT 201 & 222; 221\*; 222\*; 224;

225\*; 226\*; 227\*; 228\*; 229; 232; 234;

3RD FLOOR UNITS/SPACES: 301; 303, 304, 306; 308; 307; 309; 318; 321; 322; 325; 326; 327; 328; 332, 333; 334; **[310; 312; 313**]

**EXCLUDING SHAFT; 314; 315; 316; 329; 331;** 

4TH FLOOR UNITS/SPACES: 403; 404; 432; 433; [406; 408;

417/418; 421; 422; 425; 426; 427;

OK FOR 5/8" TYPE X GWB AT WALL ABOVE CEILING AT BACKSIDE

OF STAIRWELL AT 303, 304, 332;

## **Comments:**