LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20170794, Public Works Infrastructure Permit - Residential Eagle Creek 15th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:	Increatory	Outcome:	Date:
Inspection:	Inspector:	Outcome:	Date:
DEI-Street - Proof Roll	Tom Chandler	Partial	Wednesday, October 25, 2017
Informational			
84+00 on River Trai	5/2017 10:47 AM Proof rolle l rd. and on Ladderback driv i tomorrow for remaining ro	e. Will begin laying base	•
DEI-Subgrade Inspection	Tom Chandler	Partial	Wednesday, October 25, 2017
Informational			
1 Tom Chandler 10/2	5/2017 3.51 PM Olsson on-s	ite for testing of type 5 h	ase rock installed

1 Tom Chandler 10/25/2017 3:51 PM Olsson on-site for testing of type 5 base rock installed on Ladderback drive.

Comments: