

# Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #:PRCOM20171689, Building Permit - Commercial

Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	John Borns	Partial	Monday, October 30, 2017

Partial Correction

1 Misc

OK TO TAPE, MUD AND FIRE-STOP 5/8" TYPE X GWB AT:  
FIRE-RATED WALLS AT: OUTSIDE 1A250 AND 1A226 FROM  
CORNER TO DOOR

TOP-OUT ONLY AT: 1A212 W WALL AT DOOR #212.3; 218 N, W, S  
WALLS: 258 W WALL; 260 W WALL; 261 W WALL; 262.1 N, W  
WALLS; 262.2 W WALL;

1A232 S&E TO 10' AFF; 1A250 S/E/N TO 10' AFF; 226 COMPLETE;

ON F' FROM (15.6) TO (16.4) CORRIDOR FACE ONLY;

TOP-OUT COMPLETE @ 250; 255 N AT BACKSIDE OF 262.1; 257;  
261; 262.1; 263;

267 West, East, & North walls; 260 East wall; & 258 East wall

218 B/F; 212 N,W,S B/F; 268 E WALL; **[259 W WALL;**

<b>In-wall Inspection</b>	John Borns	Partial	Monday, October 30, 2017
---------------------------	------------	---------	--------------------------

Partial Correction

1 Misc

OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING  
+ IN-WALL SYSTEMS AT FOLLOWING SPACES/LOCATIONS: ROWS  
F THROUGH J, AND 17.3 THROUGH 16; STORAGE RM 1A226;  
RESTROOM 1A232; STORAGE RM 1A250; RESTROOM 1A217;

CLEAN RM 1A218; EXTERIOR WALL AT 1A263 & 1A268; [261;  
262.1; 262.2; 267; 218 COMPLETE; 263 COMPLETE; 210  
COMPLETE; 258; 260; CORR 259; **[209 S WALL; 213-215 E WALL;  
266 N WALL; EAST FACE OF NEW INTERIOR WALL SEGMENTS  
ALONG (E');**

**Comments:**