

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20160939, Building Permit - Commercial

Address: 3320 NE WILSHIRE DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Mark Harding	Partial	Wednesday, November 01, 2017

Corrective Action Required

1	Misc	HARD-LID CEILING SPACE BELOW RATED CEILING: -ZONE A&C CORRIDOR-OK -ZONE B-OK DROP-CEILING: -ZONE A&C CORRIDORS OK -ZONE B: FC CEILING PENETRATIONS ABOVE KITCHEN/CORRIDOR/LAUNDRY AREA AND PENETRATIONS OF SMOKE BARRIER WALL KITCHEN AND CORRIDOR SOUTH OF KITCHEN
---	------	---

Alarm Test	Joe Dir	Not Ready	Wednesday, November 01, 2017
-------------------	---------	-----------	------------------------------

Comments: