LEE'S SUMMIT

## PUBLIC WORKS ENGINEERING DIVISION

## **Inspection Summary**

Permit #: PRPWFR20171746, Public Works Infrastructure Permit - Residential Manor at Stoney Creek 2nd - street, storm, sewer and water

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
DEI-Miscellaneous PWORKS Inspection	Brice Lawson	Passed	Thursday, November 02, 2017
Informational			,

1 Brice Lawson 11/02/2017 12:34 PM

On 11/1/17 Redford performed testing of the sanitary sewer stub tracer wires for lots 60,61,62,63,64,65,66,67,68,69,70,71,82,83,84,85, 86,87,88,89,90,91,92 and 93. A locate tool was connected to a screw on each lateral tracer box and the tracer wire was locatable to the sewer main. The tracer wire boxes for these lots are attached to a green colored 2" by 4" vertical board with duct tape.

Comments: