

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20170812, Building Permit - Residential

Address: 1622 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Monday, November 06, 2017

Corrective Action Required

- | | | |
|---|------|--|
| 1 | Misc | 1. BSMT: Firestop gaps along tops of walls and at either end of the ceiling furr-out (over showers).
2. BSMT: Firestop vert-to-horiz at stair landing.
3. 1st FLR: Firestop top of fireplace chase.
4. 1st FLR: Sill-plate anchors at NW and NE corners of garage.

OK to insulate. |
|---|------|--|

Comments: