

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Address: 1801 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below.

Permit #: PRRES20171770, Building Permit - Residential

Inspection Item:
Inspection:
Inspection:

DEI-Sidewalk Inspection

Tom Chandler

Passed

Monday,
November
06, 2017

## Informational

1 Matt Munger 10/27/2017 10:43 AM

Forms were set to meet ADA standards and gravel was compacted properly. Dan is going to use Isolation Joint material in the areas that we specified.

Tom Chandler 10/31/2017 2:47 PM Looks ready to pour.

Tom Chandler 11/06/2017 10:18 AM Sidewalk has been completed and passed final inspection.

## Comments: