Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161178, Building Permit - Commercial Address: 1800 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	John Borns	Partial	Wednesday, November 08, 2017
Partial Correction			
1 Misc		OK TO POUR WHEN READY LIGHT LOCATIONS NUMBERED ON SITE THRU #49;	
Partial Correction		,	
2 Misc		OK TO COVER WHEN READY TREE L.P.#2 ONE 1" TO 80' WEST + ONE EXSTG; ONE 1" FROM PL#2 TO 45 ACROSS FRONT ENTRANCE FROM ~110' NW FOR BL; ONE 1" FROM LOCATION; ONE 1" FROM Q-BOX EAST OF ENTRANCE CANOPY; GR CONDUIT TRENCH DUE TO ROCK #11 TO #12; #13 TO #9 TO #10; FF #6 TO 15' WEST; 1" PVC FROM #1 22 TO 21; TWO 1" FROM 29 WES 1" PVC FROM NW CORNER OF PO THIS POINT TO STUB-UP AT BUILD BUILDING A EAST TO BOLLARD LI #D2 TO A POINT 20' TO THE NOR CONNECTED IN AREA OF SITE LIG BASE AND QUAZITE BOX N OF BL INSIDE-CORNER OF PATIO TO WE NORTH SIDE OF PATIO; ONE 1" PV COMMONS PATIO TO EAST SIDE OF PATIO TO NORTH, AROUND C TO L.P. #D5; FROM #36 TO 37 TO BOLL 44 TO LP 34; 42 TO 30' SE; L	E 3/4" TO 28' WEST CONN TO ' NE FOR BL; ONE 1" ~80' A BL TO BL; ONE 3/4" FROM LP#7 PL#7 NORTH 20' TO Q-BOX LOCATION NW TO BL LOCATION OUND ROD FOR LP#7 LAID IN CONDITIONS; FROM L.P.#10 TO ROM #12 TO #14 TO #15; FROM .7 TO 26 TO 25 TO 24 TO 23 TO T/NW TO PEDESTAL METER; ONE DOL BLDG TO 100' WEST - FROM DING A; FROM STUB-UP AT GHT #D2; FROM BOLLARD LIGHT TH; CONDUIT COMPLETE AND HTING METER PEDESTAL, L.P. DG "B"; ONE 1" PVC FROM ST OF POOL BLDG, EAST ALONG /C FROM NORTH SIDE OF OF FIREPIT; FROM NORTH SIDE ORNER OF FIREPIT, THEN WEST 38 TO BOLLARD #43; 28 to 36;

28 TO 29; [FROM 45 TO 20' NW;

Comments: