
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFR20170794, Public Works Infrastructure Permit - Residential
Eagle Creek 15th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Miscellaneous PWORKS Inspection	Tom Chandler	Partial	Monday, November 13, 2017

Informational

- 1 Tom Chandler 11/13/2017 9:08 AM Called and emailed the utilities contractor with the results of the video inspection from the water utilittes department. There is (1) small sag and some debris in the main that needs to be corrected as well as (8) service wyes that need to be corrected to meet the 30-45 degree limits.

Comments:
