

KRUGER TECHNOLOGIES, INC.**REPORT OF SPECIAL INSPECTION**

Client: John Knox Village **Address:** 602 NW Pryor Rd
Lee's Summit, MO 64081

Project: John Knox Village – Meadows **Project Number:** 216095C.519

Date Tested: 10/18/2017 **Date Reported:** 10/19/2017 **Technician:** SWB

A KTI Representative was on site for out of scope observation of tie downs wing A at floors 3 and 4 north of the knuckle and floors 3, 4 and 5 south of the knuckle. Tie downs appear to be present and in line with holdowns on the 2nd floor as required. Locations requiring tightening were tightened while the technician was on site bringing tie downs to acceptable condition.

Respectfully submitted,
KTI-Kruger Technologies, Inc.



Otto J. Kruger, Jr., P.E.