

# Certificate of Occupancy

---

**Permit #:** PRCOM20170985  
**Address:** 1706 NW CHIPMAN RD, LEES SUMMIT, MO 64081  
**Inspected On:** Tuesday, November 14, 2017  
**Inspected By:** John BornsJohn Borns

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
<b>Above Ceiling Inspection</b>	John Borns	Passed	Tuesday, November 14, 2017
<b>Occupancy Inspection - Codes Commercial</b>	John Borns	Full C of O	Tuesday, November 14, 2017

**Comments:** REMOVE ABANDONED GROUNDING ELECTRODE CONDUCTOR FROM ABOVE CEILING IN IT ROOM. THEN OK FOR IT ROOM CEILING TO BE PLACED AND FOR FULL OCCUPANCY.