

Inspection Summary

Permit #: PRCOM20161058, Building Permit - Commercial
Address: 1200 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	Mike Copeland	Not Ready	Wednesday, November 15, 2017
Partial Correction 1 Misc		NOT A COMPLETE FINAL, INSPECTED RECEPTACLES THAT MAY BY COVERED WITH OFFICE FURNITURE. OKAY TO INSALL OFFICE FURNITURE ONLY	
Alarm Test	Joe Dir	Passed	Wednesday, November 15, 2017
Sprinkler - Flow Test	Joe Dir	Passed	Wednesday, November 15, 2017

Comments: