

Certificate of Occupancy

Permit #: PRRES20171226
Address: 611 NW REDBUD DR, Unit:A, LEES SUMMIT, MO 64081
Inspected On: Friday, December 01, 2017
Inspected By: John BornsJohn BornsJohn Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	John Borns	Full C of O	Friday, December 01, 2017
Plot Plan Inspection	John Borns	Passed	Friday, December 01, 2017
Erosion Control	John Borns	Passed	Friday, December 01, 2017

Comments: