

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Address: 1820 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

Permit #: PRRES20171896, Building Permit - Residential

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item: Inspection:	Inspector:	Outcome:	Date:
Driveway Inspection	Tom Chandler	Partial	Tuesday, December 05, 2017

## Informational

Tom Chandler 12/05/2017 9:28 AM Inspected forms and compacted aggregate only. Contractor notified to blanket and maintain temperature throughout cure process.

## **Comments:**