

## **PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

Permit #: PRRES20162861, Building Permit - Residential

Address: 3333 SW JESSIE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:
Inspection:

Inspection:

Date:

Del-Sidewalk Inspection

Brice Lawson

Partial

Wednesday,
December
06, 2017

## Informational

1 Brice Lawson 12/06/2017 10:26 AM

The sidewalk forms are set. The rock has been compacted. It appears that the sidewalk is formed to the edge of the property. There is no way to know for sure as there is no curb show showing the corner of the lot. I let Gary know that the temperatures are going to be low and the sidewalk needs to be covered with blankets.

## Comments: