

# Certificate of Occupancy

---

**Permit #:** PRCOM20171543  
**Address:** 221 NW CHIPMAN RD, LEES SUMMIT, MO 64063  
**Inspected On:** Tuesday, December 12, 2017  
**Inspected By:** John BornsMichael Weissenbach

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Commercial	John Borns	Full C of O	Tuesday, December 12, 2017
Occupancy Inspection - Fire	Michael Weissenbach	Passed	Tuesday, December 12, 2017

**Comments: ONE ISSUE (LOWERING OF BACKFLOW PREVENTION DEVICE AT BASEMENT) TO BE RESOLVED DIRECTLY WITH LSWU. ISSUE COFO.**