

Inspection Summary

Permit #: PRCOM20172339, Building Permit - Commercial
Address: 300 SW BLUE PKWY, Unit:D, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| | | | |
|---|---------------|----------|----------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Electrical Service Inspection - Commercial | Mike Copeland | Passed | Tuesday, December 19, 2017 |

| | | | |
|-------------------------------------|---------------|---------|----------------------------|
| Above Ceiling Inspection | Mike Copeland | Partial | Tuesday, December 19, 2017 |
|-------------------------------------|---------------|---------|----------------------------|

Partial Correction
1 Misc

OK TO COVER WHEN READY GWB CEILING / SOFFIT / BULKHEAD FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING LOCATIONS: BULKHEAD @ HIPS/ABS/ STRETCHING E/SW/S; REMAINING NARROW SOFFITS AT SOUTH; [HANGING STRUCTURE AT FRONT VESTIBULE;

Partial Correction
2 Misc

OK TO COVER WHEN READY ACT CEILING FRAMING + ABOVE-CEILING SYSTEMS @: 103A - 103C; 104 - 109; 111A - 111H; 112A; 115A - 115C; 116 FRONT DESK;

Partial Correction
3 Misc

JANIOR AREA BETWEEN LOCKER ROOMS, OFFICE, CHECK IN DESK AREA AND ENTRANCE AREAS APPROVED.

Comments: