

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20170916, Building Permit - Commercial

Address: 2100 SE BLUE PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---------------------------|---------------|----------|----------------------------|
| In-wall Inspection | Mike Copeland | Partial | Thursday, January 11, 2018 |

Partial Correction

| | | |
|---|------|---|
| 1 | Misc | -2ND FLOOR EXISTING BUILDING, 2 ROOMS APPROVED TO COVER ADJACENT TO SMOKE BARRIOR |
|---|------|---|

Partial Correction

| | | |
|---|------|--|
| 2 | Misc | 3RD FLOOR: ; DATA AND ELECTRIC ROOM APPROVED; WEST WING STAIR APPROVED. APPROVED ALL EXTERIOR WALLS. -NORTH MECHANICAL, EQUIPMENT, EAST STAIR APPROVED -SOUTH WING FROM J6 TO LINE 11, MINUS STAIR. REPAIR FIRE PROTECTION FOR STEEL COLUMN AT STAIR -RM 3-126, 3-128 TO 3-139, 141 -WEST WING:3-101 THRU 3-120, 3-140 THRU 3-154 -APPROVED TO TOP OUT CORRIDORS WEST WING. WEST WING PATIENT ROOMS APPROVED TO COVER |
|---|------|--|

Rated Assembly Inspection

| | | |
|---------------|---------|----------------------------|
| Mike Copeland | Partial | Thursday, January 11, 2018 |
|---------------|---------|----------------------------|

Partial Correction

| | | |
|---|------|---|
| 1 | Misc | LINE 6 (2 HOUR WALL) WITNESSED ASSEMBLY OF FIRE INSULATION AND SPRAY BETWEEN AIR GAP IN 2 HOUR WALL. -ROOF TOP FIRESTOP APPROVED |
|---|------|---|

Partial Correction

| | | |
|---|------|---|
| 2 | Misc | SOUTH MECHANICAL ROOM (2 HOUR): NORTH FACE, TOP OUT SCREW PATTERN APPROVED 1ST LAYER (TOP 6 FEET) |
|---|------|---|

Partial Correction

| | | |
|---|------|-----------------------------------|
| 3 | Misc | WEST ELEVATOR SHAFT: ALL APPROVED |
|---|------|-----------------------------------|

Partial Correction

4 Misc

SOUTH STAIR TOWER, FIRST LAYER SHAFT WALL APPROVED, 2ND LAYER APPROVED, NEED TO INSPECT WHERE FRAMING AROUND LANDING AREA

Partial Correction

5 Misc

ELEVATOR A, B: SHAFT WALL APPROVED, 2nd LAYER GYP BOARD APPROVED

Comments: