Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20173335, Building Permit - Residential Address: 1709 NE PARKWOOD DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date: Inspector: **Electrical Service** Khanh Nguyen Tuesday, January 16, 2018 Passed **Inspection - Residential** Gas Service Inspection - Khanh Nguyen Passed Tuesday, January 16, 2018 Residential All Rough Inspection -Khanh Nguyen Failed Tuesday, January 16, 2018 Residential

Corrective Action Required

1 Misc Fi

FRAMING:

-GARAGE PPRTAL FRAME WALLS-NAIL SHEATHING PER CODE
-STRAP GARAGE WALL TOP PLATES LAPPED LESS THAN 24"
-EXTERIOR DOORS: INSTALL SECURITY BLOCKINGS; FILL IN WITH
WOOD GAPS AT STRIKE PLATES AND HINGES PER SECURITY CODE
-FIREBLOCK FLOOR AT DRYER DUCT; FIREBLOCK BASEMENT WALL
VERTICALLY SPACE EVERY TEN FT; FB EAST BASEMENT WALL
FROM FURDOWN SPACE; FB WALL ABOVE WET BAR SINK

PLUMBING:

-INSTALL STUD SHOE AT OVERBORED STUD AND PROTECT PLUMBING ADJACENT TO KITCHEN SINK

MECHANICAL:

- -PROVIDE RETURN AIR FROM FRONT BEDROOM
- -CONNECT DUCT TO BATHFAN IN BASEMENT BATH
- -PAN OFF RETURN AIR SPACE FROM CEILING FURDOWN SPACE

ABOVE FRONT BASEMENT BED

-INSTALL SUPPLY REGISTER AT CEILING LEVEL ABOVE BASEMENT SHARED BATHROOM

ELECTRICAL:

-PROTECT WIRING RUNNING ACROSS JOISTS AND STUDDINGS WHERE WITHIN SIX FT OF ATTIC ACCESS
-PROTECT WIRING AT WALL TOP PLATES ABOVE&BEHIND SERVICE PANEL

**OK TO INSULATE

Comments: