

Certificate of Occupancy

Permit #: PRCOM20174120
Address: 611 SW 3RD ST, Unit:B, LEES SUMMIT, MO 64063
Inspected On: Monday, January 29, 2018
Inspected By: John BornsMichael WeissenbachJohn BornsJohn Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Monday, January 29, 2018
Occupancy Inspection - Michael Fire	Michael Weissenbach	Passed	Monday, January 29, 2018
Occupancy Inspection - John Borns Codes Commercial	Not Ready		Monday, January 29, 2018
Occupancy Inspection - John Borns Codes Commercial	Partial		Monday, January 29, 2018

Comments: CURRENT, LEGIBLE, ACCURATE PANEL SCHEDULES REQUIRED AT ELECTRICAL PANELS.

OCCUPANT TO MAKE BALCONY GUARD COMPLIANT WITH COMMERCIAL CODE AS SOON AS WEATHER ALLOWS. CALL IF QUESTIONS.