

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWLD20173826, Public Works Land Disturbance Permit

TAILOR MADE LANDING

Address: 1600 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Matt Munger	Failed	Tuesday, January 30, 2018

Corrective Action Required

- 1 Matt Munger 01/30/2018 11:18 AM Silt fence along SE Hamblen Rd. needs to be pulled back up. Large dirt chunks from spoil piles on the property have fallen over onto the silt fence causing the fence to fall over. ESC needs to be maintained weekly.

Comments: