

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20172815, Building Permit - Residential

Address: 1813 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Electrical Service Inspection - Residential	Mike Copeland	Passed	Friday, February 02, 2018

All Rough Inspection - Residential	Mike Copeland	Failed	Friday, February 02, 2018
---	---------------	--------	---------------------------

Corrective Action Required

1	Misc	-STRAP GARAGE PORTAL -SECURITY BLOCK GARAGE WALK OUT DOOR -INSTALL ATTIC ACCESS 3RD GARAGE -BUILDING SEWER CLEANOUT LOCATED UNDER THE BASEMENT LANDING, MUST BE ACCESSABLE, SAME WITH WATER SERVICE ENTRY -BEAM IN BASEMENT REQUIRES BEARING FOR THE ENTIRE WIDTH OF THE BEAM -TOP OF 2ND FLOOR LANDING, STRAP TOP PLATES WHERE TRANSITION FROM 2x6 STUD WALL TO 2x4
---	------	---

OKAY TO INSULATE

Gas Service Inspection - Residential	Mike Copeland	Passed	Friday, February 02, 2018
---	---------------	--------	---------------------------

Gas Piping Inspection - Residential	Dale Carter	Passed	Friday, February 02, 2018
--	-------------	--------	---------------------------

Erosion Control

Mike Copeland

Partial

Friday, February 02, 2018

Partial Correction

1

Misc

Erosion control compliant, please maintain

Comments: