
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSITE20180201, Development - Site

Address: 1600 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Sanitary - Material Verification	Matt Munger	Partial	Wednesday, February 14, 2018

Informational

- 1 Matt Munger 02/14/2018 8:54 AM John D. and I looked at the materials that were on site. There was approximately 630 Linear Feet of SDR-26 sanitary sewer pipe on site. We observed SDR-26 fittings and Wye connections.

DEI-Sanitary - Material Verification	John DiMauro	Partial	Wednesday, February 14, 2018
--------------------------------------	--------------	---------	------------------------------

Informational

- 1 Matt M. and I looked at the materials that were on site. There was approximately 630 Linear Feet of SDR-26 sanitary sewer pipe on site. We observed SDR-26 fittings and Wye connections.

Comments:
