

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSITE20180201, Development - Site

Address: 1600 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|--------------------------------------|-------------|----------|-----------------------------|
| DEI-Sanitary - Material Verification | Matt Munger | Partial | Thursday, February 15, 2018 |

Informational

- 1 Matt Munger 02/15/2018 9:35 AM John D. and I looked over the casing pipe and I measured the thickness of the 16" Dia pipe and it was close to 3/8" exceeding the 3/16" minimum wall thickness.

The casing spacers were onsite and they were CCI Pipeline Systems Order# 18-0747, Carrier O.D. 8.40" and Casing ID 15.25.

Work had not started yet on the boring process.

Comments: