

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRRES20171830, Building Permit - Residential

Address: 1853 SW BLACKSTONE CT, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mike Copeland	Failed	Tuesday, February 27, 2018

Corrective Action Required

- | | | | |
|---|------|-----|--|
| 1 | Misc | 1. | Hoist hanger ceiling joists over garage door. |
| | | 2. | Protect plumbing water master shower, laundry. |
| | | 3. | No listed ground connections in any boxes. |
| | | 4. | Top plate master sink overdrilled. |
| | | 5. | Flash south plumbing vent. |
| | | 6. | Valley rafters need support at the ridge. |
| | | 7. | Vent future basement plumbing. |
| | | 8. | Solid block floor joists over beams. |
| | | 9. | Solid block rear cantilever. |
| | | 10. | Secure fireplace to framing. |

Electrical Service Inspection - Residential	Mike Copeland	Passed	Tuesday, February 27, 2018
--	---------------	--------	----------------------------

Comments: