

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20173386, Building Permit - Residential

Address	: 1530 SW BLACKST	ONE PL, LEES SUMMIT, M	O 64082	
			ults noted below. Please c not cover any work until a	
Inspection Item: Inspection:		Inspector:	Outcome:	Date:
Driveway Inspection		Tom Chandler	Partial	Thursday, March 01, 2018
Informat 1		/01/2018 8:43 AM Inspec	ted forms and compacted	aggregate only.
DEI-Sidewalk Inspection		Tom Chandler	Failed	Thursday, March 01, 2018
Informat 1	Tom Chandler 03/01/2018 2:30 PM Inspected forms and compacted aggregate only. ADA landing that was installed with the developement is not compliant. Will need to remove and replace. There are a couple of areas that I marked in paint that not compliant for cross slope. Contractor to make corrections and will reinspect in the morning. Called contractor to notify that corrections are needed.			
Comme	nts:			