

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Address:				
This work has been inspected	and the inspection result	s noted below. P	lease call for re	e-inspection

once all corrective actions have been completed. Do not cover any work until approved.

Permit #: PRSUBD20180158, Development - Subdivision

Park Ridge 6th Plat

Informational

Jeremy Young 02/27/2018 1:16 PM Spoke with contractor about ESC devices. The contractor has installed silt fencing around the perimeter of the site. The contractor will also be mulching trees and using the mulch for ESC in other areas of the site. They have established a good construction entrance to keep the debris off of the street.

Informational

2 Jeremy Young 03/08/2018 11:19 AM Contractor is working to complete the ESC as called out in plans. They have removed and ground trees for mulch that will be used for ESC. The contractor will take what precautions are needed for the detention basin. Will re-inspect.

Comments: