Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20171689, Building Permit - Commercial Address: 100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

In-wall Inspection John Borns Partial Friday, March 09, 2018

Partial Correction

1 Misc OK TO COVER WHEN READY LIGHT-GAUGE STEEL WALL FRAMING

+ IN-WALL SYSTEMS AT FOLLOWING SPACES/LOCATIONS: ROWS F THROUGH J, AND 17.3 THROUGH 16; STORAGE RM 1A226; RESTROOM 1A232; STORAGE RM 1A250; RESTROOM 1A217; CLEAN RM 1A218; EXTERIOR WALL AT 1A263 & 1A268; 261; 262.1; 262.2; 267; 218 COMPLETE; 263 COMPLETE; 210

COMPLETE; 258; 260; CORR 259; 209 S WALL; 213-215 E WALL; 266 N WALL; 266 W WALL B/F; 256 N WALL B/F; 1A044 E; 1A200-203; 206-207; 256 S; **[S WALL AT 1A255 FROM D' TO E'**

BOTH FACES;

Above Ceiling John Borns Partial Friday, March 09, 2018 **Inspection**

Partial Correction

1 Misc OK TO COVER WHEN READY GWB CEILING / SOFFIT / BULKHEAD

FRAMING + ABOVE-CEILING SYSTEMS @ FOLLOWING SPACES:

SOFFITS AT NURSE STATIONS 208&222: FRAMING & SPRINKLER

PIPING ONLY AT THREE WEST SOFFITS;

OR 258; OR 260; [SOFFIT AT NURSE STN #2 @ 1A208;

Partial Correction

2 Misc OK TO COVER WHEN READY ACT CEILING FRAMING +

ABOVE-CEILING SYSTEMS @: 1A216; 219-239; 250; 257; 261;

262.1; 263; 267; 268; 266;

PHASE INTERFACE AREAS: [1A256 SUBSTERILE CORRIDOR N 1/2; INTERSECTION AREA OF CORR 251 & 257; NURSE STATION AREA S

OF RECOVERY

Comments: