

---

**PUBLIC WORKS ENGINEERING DIVISION**

## **Inspection Summary**

---

Permit #: PRSUBD20180158, Development - Subdivision

Park Ridge 6th Plat

Address:

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
DEI-Site Visit	Jeremy Young	Partial	Monday, March 12, 2018

Informational

- 1 Jeremy Young 03/12/2018 10:57 AM John DiMauro and myself met with the contractor to make introductions. The contractor is clearing dirt and rock for storm line installation. This should begin tomorrow.

**Comments:**

---