

Certificate of Occupancy

Permit #: PRRES20171228
Address: 617 NW LILAC PL, LEES SUMMIT, MO 64081619 NW LILAC PL, LEES SUMMIT,
MO 64081615 NW LILAC PL, LEES SUMMIT, MO 64081
Inspected On: Tuesday, March 13, 2018
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

| | | | |
|--|-------------|----------|----------------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Occupancy Inspection - John Borns Codes Residential | Full C of O | | Tuesday, March 13, 2018 |

Comments: UNITS 615; 617; 619 OK FOR USE & OCCUPANCY. ISSUE COFO.