

# Temporary Certificate of Occupancy

---

**Permit #:** PRCOM20172339  
**Address:** 300 SW BLUE PKWY, Unit:D, LEES SUMMIT, MO 64063  
**Inspected On:** Thursday, March 15, 2018  
**Inspected By:** John Borns  
**Expiration Date:** 4/26/2018 12:00:00 AM

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
<b>Occupancy Inspection - Codes Commercial</b>	John Borns	Temporary C of O	Thursday, March 15, 2018

**Corrective Action Required:**

1	Misc	ROOFTOP FINAL INSPECTION: - REMOVE ABANDONED EQUIPMENT AND MATERIAL - CONTACT HECTOR SOTO @ 816-969-1238 TO REQUEST LS PLANNING INSPECTION OF COMPLETED RTU SCREENING - RTU SCREENS ARE NOT SECURED TO ROOF STRUCTURE - FINAL CLEAN ALL DEBRIS AND LOOSE MATERIAL FROM PLANET FITNESS ROOFTOP FOOTPRINT
---	------	---

**Corrective Action Required:**

2	Misc	IFGC 407; 415: PROTECTION OF ROOF MEMBRANE UNDER WOODEN PIPING SUPPORT BLOCKS FOR ROOFTOP EQUIPMENT AND GAS PIPING: APPLY SPECIFIED / APPROVED, ROOF-COMPATIBLE SLIP SHEET TO UNDERSIDE OF BLOCKS WITH METAL FASTENERS AT SIDES OF BLOCKS.
---	------	--

SOME WOOD BLOCKS LACK SLIP SHEETS.

**TEMPORARY OCCUPANCY CERTIFICATE EXTENDED TO ACCOMODATE RESOLUTION OF ABOVE ISSUES.**