

Certificate of Occupancy

Permit #: PRCOM20173173
Address: 1150 NE DOUGLAS ST, LEES SUMMIT, MO 64086
Inspected On: Friday, March 16, 2018
Inspected By: John Borns

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - John Borns Codes Commercial	Full C of O		Friday, March 16, 2018

Comments: PENETRATIONS OF EAST EXTERIOR WALL ARE TO BE SEALED.

NOTED: LIGHT-GAUGE STEEL FRAMING AND ENCLOSED SYSTEMS AT WEST AND EAST CANOPIES WERE NOT REQUESTED FOR INSPECTION BEFORE COVERING. COMPOSITION / CONDITION ARE UNKNOWN.