

Development Services Department

220 SE Green Street Lee's Summit, MO 64063

(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161771, Building Permit - Commercial
Address: 819 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Monday, March 19, 2018

Partial Correction
1 Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB AT STAIRWELLS:
SOUTH STAIRWELL:
BASEMENT: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY;
1ST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER INCLUDING PRE-ROCK;
2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY;
3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER;
4TH FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER; **[BACK FACE AT UNITS AND CORRIDOR 1ST LAYER; TOWER & LANDING: [1ST LAYER AT HIGH & LOW CEILINGS & TOWER WALLS;**

NORTH STAIRWELL:
BASEMENT: S & E WALLS - 1ST LAYER INCLUDING PRE-ROCK; S & E WALLS - 2ND LAYER; N & W WALLS - 1ST LAYER; N WALL - 2ND LAYER
1ST FLOOR: 2ND LAYER INCLUDING PRE-ROCK;
2ND FLOOR: 2ND LAYER PRE-ROCK ONLY;
3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER;
4TH FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER; **[BACK FACE AT UNITS AND CORRIDOR 1ST LAYER; TOWER & LANDING: [1ST LAYER AT HIGH & LOW CEILINGS & TOWER WALLS;**

Partial Correction
2 Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB AT ELEVATOR:

SHAFT FACE / LID: 1ST LAYER FULL HEIGHT; 2ND LAYER FULL HEIGHT

SHAFT LID: 3 LAYERS + HAT CHANNEL; 4TH LAYER

**BACK FACE AT UNITS AND CORRIDOR:
[4TH FLOOR 1ST LAYER;**

Partial Correction
3 Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB AT CEILINGS & WALLS THROUGHOUT AT:

Comments: