

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Address:				
This work has been	inspected and the inspe	ction results noted belov	v. Please call for i	re-inspection

once all corrective actions have been completed. Do not cover any work until approved.

Permit #: PRSUBD20180158, Development - Subdivision

Park Ridge 6th Plat

Inspection Item:
Inspection:

Inspector:

Outcome:

Date:

DEI-Sanitary Sewer

Construction Inspection

Jeremy Young

Partial

Tuesday,

March 20,

2018

Informational

Jeremy Young 03/20/2018 11:23 AM Contractor has begun working on Sanitary Line B. They have run approximately 50' of line. There is at least 6" of rock surrounding the sanitary line. The pipe is SDR-26 and Manufactured within the last year. The pipe size is 8".

Comments: