

---

**PUBLIC WORKS ENGINEERING DIVISION**

## **Field Engineering Inspections Site Visit**

---

Permit #: PRSITE20180252, Development - Site

TAILOR MADE LANDING

Address: 1600 SE HAMBLER RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection Item:

<b>Inspection:</b>	<b>Inspector:</b>	<b>Outcome:</b>	<b>Date:</b>
DEI-Miscellaneous PWORKS Inspection	Matt Munger	Partial	Tuesday, March 20, 2018

Informational

1 Matt Munger 03/20/2018 2:33 PM

No activity on site. The contractor had set the vault for the Backflow Preventer. The pit on either side of the road was full of water.

**Comments:**

---