LEE'S SUMMIT

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRRES20173776, Building Permit - Residential

Address: 1713 NE PARKWOOD DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

is a clean joint	Jeremy Young /2018 11:45 AM Contractor I at the ROW line. The cross sl here will be at least 6" of cor	lope for the ADA requiremer	
is a clean joint	at the ROW line. The cross sl	lope for the ADA requiremer	
spection	Jeremy Young	Partial	Thursday, March 22, 2018
		-	
ction -	Khanh Nguyen	Failed	Thursday, March 22, 2018
calls for triple L		ove front bed	
i	y Young 03/22, s between .04 ction - Required NG: engineer checl	y Young 03/22/2018 11:49 AM Contractor I s between .04-1.2% through out the sidew ction - Khanh Nguyen Required NG: engineer check roof support beam size abo calls for triple LVL beam below foyer.	y Young 03/22/2018 11:49 AM Contractor has at least 4" compacted ro s between .04-1.2% through out the sidewalk which meets ADA require ction - Khanh Nguyen Failed Required NG: engineer check roof support beam size above front bed calls for triple LVL beam below foyer.

Comments: