
PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRSUBD20180642, Development - Subdivision

PERGOLA PARK, 4TH PLAT

Address: 3200 SW PERGOLA PARK DR, LEES SUMMIT, MO 640811003 SW REDBUCK CIR, LEES SUMMIT,
MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
Site Visit Inspection	Tom Chandler	Passed	Tuesday, April 03, 2018

Informational

1 Tom Chandler 04/03/2018 9:05 AM No work being performed today. ESC devices installed according to plan phase 1 and working properly.

Comments:
