Development Services Department

220 SE Green Street Lee's Summit, MO 64063
(816) 969-1200   FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161771, Building Permit - Commercial
Address: 819 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	John Borns	Partial	Tuesday, April 03, 2018

Partial Correction

1   Misc

OK TO COVER WHEN READY 5/8" TYPE X GWB AT STAIRWELLS:
SOUTH STAIRWELL:
BASEMENT: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY;
1ST FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER INCLUDING PRE-ROCK;
2ND FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER PRE-ROCK ONLY;
3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER;
4TH FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER; BACK FACE AT UNITS AND CORRIDOR 1ST LAYER;
TOWER & LANDING: 1ST LAYER AT HIGH & LOW CEILINGS & TOWER WALLS; 2ND LAYER AT HIGH & LOW CEILINGS & TOWER WALLS; 3RD LAYER + HAT CHANNEL AT HIGH & LOW CEILINGS; 4TH LAYER AT HIGH & LOW CEILINGS

NORTH STAIRWELL:
BASEMENT: S & E WALLS - 1ST LAYER INCLUDING PRE-ROCK; S & E WALLS - 2ND LAYER; N & W WALLS - 1ST LAYER; N WALL - 2ND LAYER
1ST FLOOR: 2ND LAYER INCLUDING PRE-ROCK;
2ND FLOOR: 2ND LAYER PRE-ROCK ONLY;
3RD FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER;
4TH FLOOR: 1ST LAYER INCLUDING PRE-ROCK; 2ND LAYER; BACK FACE AT UNITS AND CORRIDOR 1ST LAYER;
TOWER & LANDING: 1ST LAYER AT HIGH & LOW CEILINGS & TOWER WALLS; 2ND LAYER AT HIGH & LOW CEILINGS & TOWER

WALLS; 3RD LAYER + HAT CHANNEL AT HIGH & LOW CEILINGS; 4TH LAYER AT HIGH & LOW CEILINGS

Partial Correction
2   Misc   OK TO COVER WHEN READY 5/8" TYPE X GWB AT ELEVATOR:

SHAFT FACE / LID: 1ST LAYER FULL HEIGHT; 2ND LAYER FULL HEIGHT

SHAFT LID: 3 LAYERS + HAT CHANNEL; 4TH LAYER

Partial Correction
3   Misc   OK TO COVER WHEN READY 5/8" TYPE X GWB AT CEILINGS & WALLS THROUGHOUT AT:
4TH FLOOR; 3RD FLOOR; **[2ND FLOOR;**

GWB AT SHEAR WALLS, BACKSIDE OF STAIRWELL AND ELEVATOR WALLS AT UNITS & CORRIDOR: 4TH FLOOR 1ST LAYER; 3RD FLOOR 1ST LAYER; 2ND FLOOR 1ST LAYER;

Comments: